






*FOR GREASE INSTRUCTION SEE PZ4113

Strongest compression spring mounted at delivery

Comment: Max torque 50 Nm. Max speed 700 r.p.m

11	0211 1171 00	2	HEX SOCK SCREW	MC6S M4x12 12.9
10	4230 2667 00	1	CABLE RAIL	QST42 COT
9	4230 2982 80	1	OFFSET GEAR	QDOT38-050 i=1,000
8	0211 1174 00	2	HEX SOCK SCREW	MC6S M4x20 12.9
7	4230 2644 11	1	CABLE RAIL	QST 42-50
6	4230 1480 00	1	GREASE	KERNITE Lubra K HS*
5	4230 1825 01	1	COMPRESSION SPRING	11-22N
4	4230 1825 00	1	COMPRESSION SPRING	29-40N
3	4230 1819 00	1	SOCKET HOLDER	QM.42: 1/2": ±0 :tra.50: hole
2	4230 2170 81	1	GEAR UNIT	"42": i=21.33 (((39/9)+1)*((39/13)+1)))
1	4230 3011 80	1	MOTOR	QST 42
Pos	Designation	Number	Name	Comment

Tolerances, if not indicated, according to:	-	-	-	-	-
AC-STD	-	-	-	-	-



Name QST42-50COT-T50-L134-H13				QST		Secrecy class	
Material -				1102 K/-		Drawing owner	
-				CAD Pro/E		T00	
Scale 9:20		Format A3		Family MK2_G		Compare -	
Drawn tooten		Blank -		Replaces -		Sheet 1 (2)	
Cons.class 1295 K/-		Rev 4		Status RELEASED		Designation	
Mass/Volume 4.8 kg		Date 2006-12-21		8435		6030 20	

4	-	Motor & Offset Gear replaced = MK2	2013-03-04	CSR
Note	Pos.	Modified from	Date	Intr.

Model name	8435603020	Rev.Ver	4.1
Drawing name	8435603020	Rev.Ver	4.1

This document is our property and shall not without our permission be altered, copied, used for manufacturing or communicated to any other person or company.

4	-	Motor & Offset Gear replaced = MK2	2013-03-04	CSR
Note	Pos.	Modified from	Date	Intr.



Tolerances, if not indicated, according to:		-	-	-	-	-
AC-STD		-	-	-	-	-
Name QST42-50COT-T50-L134-H13					QST	Secrecy class
Material -					1102 K/-	
-					CAD Pro/E	
	Scale	1:2	Format	A3	Family	MK2_G
	Drawn	tooten	Blank	-	Compare	-
	Cons.class	1295 K/-	Rev	4	Replaces	-
Transferred from		SW	Mass/Volume	4.8 kg	Status	RELEASED
			Date	2006-12-21	Designation	8435 6030 20
					Sheet 2 (2)	
					Drawing owner	
					T00	