


*FOR GREASE INSTRUCTION SEE PZ4113

Strongest compression spring mounted at delivery
Comment: Max torque 230 Nm. Max speed 330 r.p.m

11	4230 1480 00	1	GREASE	KERNITE Lubra K HS*
10	0211 1176 00	2	HEX SOCK SCREW	MC6S M4x25 12.9
9	0211 1965 27	2	HEX SOCK SCREW	MC6S M4x18 H 12.9
8	4230 2669 00	1	CABLERAIL	QST62-COT
7	4230 2647 10	1	CABLE RAIL	QST 62
6	4230 1827 01	1	COMPRESSION SPRING	QMX62 80 : 18-30N
5	4230 1827 00	1	COMPRESSION SPRING	QMX62 80 : 48-60N
4	4230 1822 00	1	SOCKET HOLDER	QMX62: 3/4" 0mm 50mm travel QM62 thru hole.
3	4230 2984 80	1	OFFSET GEAR	QDOT62-200 i=1.00 300Nm
2	4230 2172 81	1	GEAR UNIT	QMX62 l=19.04 = ((41/15+1)*(41/10+1))
1	4230 3013 80	1	MOTOR	QST 62

Pos	Designation	Number	Name	Comment
Tolerances, if not indicated, according to:				
AC-STD				
Name QST62-230COT-T50-L152-H19				Secrecy class
Material				1102 K/-
				CAD Pro/E
Scale 1:3		Format A3	Family MK2_G	Compare
Drawn tooten		Blank		Replaces
Transferred from SW		Cons.class 1295 K/-	Rev 5	Status
		Mass/Volume 13.2 kg	Date 2006-12-21	Designation
				Sheet 1 (2)
				8435 6065 20

5	-	New connector: Motor & Offset Gear replaced = MK2	2013-03-05	ASH
Note	Pos.	Modified from	Date	Intr.

